

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2016 Levee Inspection Results

Reclamation District No. 2058 Pescadero

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2016 Levee Inspection Results

Reclamation District No. 2058 Pescadero

Waterway			Bank	Unit Miles
Unit No. 01 Paradise Cut			Left	6.58
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/22/2016 - 3/22/2016			
DWR Inspector	Maksim Khashchuk			
Accompanied By	Greg Pombo RD2058			
	Joe Navaro RD2058			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start		Rating **	A	Issue No.	6
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD2058_01_s _ 2013_6				
Comment Code					
Inspector Comment					
The LMA has current flood fight training.					

No Photos

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD2058_01_s _ 2013_7				
Comment Code					
Inspector Comment					
Flood fight supplies are available on-site at the office.					

No Photos

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD2058_01_s _ 2013_9				
Comment Code					
Inspector Comment					
The O&M Manual is available at the district office.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	0.23	Rating **	M	Issue No.	4
LM End	0.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.804351 °	37.804351 °
				-121.418433 °	-121.418433 °
DWR ID	DWR_RD2058_01_f_2013_4				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Wild rose on the levee. This area is riparian rabbit habitat.					

Photo 1 of 1 : SP_2016_RD2058_111_4_20160229_00004.jpg



View of the wild rose habitat for the brush rabbit.

LM Start	0.25	Rating **	M	Issue No.	19
LM End	0.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.804461 °	37.804756 °
				-121.418241 °	-121.417384 °
DWR ID	DWR_RD2058_01_s_2016_19				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD2058_111_19_20160324_00038.jpg



View of the vegetation on the landside levee slope.

LM Start	0.41	Rating **	M	Issue No.	21
LM End	0.45	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.803799 °	37.803436 °
				-121.415675 °	-121.415283 °
DWR ID	DWR_RD2058_01_s_2016_21				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD2058_111_21_20160324_00039.jpg



View of the vegetation on the landside levee slope and toe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	0.72	Rating **	M	Issue No.	976
LM End	0.72	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.801792 °	37.801792 °
				-121.410921 °	-121.410921 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:45843
DS_ID:22700
EP_NO: 5055
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Excessive oil leakage.
FIELD_STRUCT_DESC: 16-inch steel stormdrain pipe through levee 3.8 feet below crown. Pump on concrete sump on landside. Siphon breaker under protective cover on the waterward slope (Permit No. 5055, 1666).
FS Date: 5/12/2015

LM Start	0.72	Rating **	M	Issue No.	976 (cont)
LM End	0.72	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_SP_2016_45843_45165.jpg



LS view: exposed pipe and vertical pump on concrete sump on drain ditch.

Photo 2 of 2 : UCIP_SP_2016_45843_74061.jpg



LS view: closeup of pump showing excessive oil leakage.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	1.21	Rating **	M	Issue No.	977
LM End	1.21	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.802249 °	37.802249 °
				-121.402183 °	-121.402183 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:45847					
DS_ID:22693					
EP_NO: 10426					
Repair Type: Non-Urgent					
Crossing Status: Indicator Found					
UCIP Comments: Crossing needs to be marked.					
FIELD_STRUCT_DESC: 33-inch steel sewer pipe through levee 17.0					
feet below crown. Manholes visible along Delta Ave but no other					
indicators visible at levee (Permit No. 10426, 1975).					
FS Date: 5/12/2015					

Photo 1 of 1 : UCIP_SP_2016_45847_74322.jpg



View of LS. Alignment of Crossing to right of canal at dirt access road.

LM Start	1.22	Rating **	U	Issue No.	978
LM End	1.22	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.802301 °	37.802301 °
				-121.401977 °	-121.401977 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:45850 DS_ID:22694 EP_NO: 11546 Repair Type: Urgent Crossing Status: Found UCIP Comments: Erosion on west side of pipe at W/S toe. FIELD_STRUCT_DESC: 18-inch steel stormdrain pipe through the levee 2-feet below the crown. Pump in ditch on the landward side. Siphon breaker on waterside shoulder. Electrical service pole at the landward toe. Permit No. 11546, 1976. FS Date: 5/13/2015					

Photo 1 of 2 : UCIP_SP_2016_45850_45171.jpg



WS view: siphon breaker hole. Siphon breaker removed for repair.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**


Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	1.22	Rating **	U	Issue No.	978 (cont)
LM End	1.22	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.802301 °	37.802301 °
				-121.401977 °	-121.401977 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:45850 DS_ID:22694 EP_NO: 11546 Repair Type: Urgent Crossing Status: Found UCIP Comments: Erosion on west side of pipe at W/S toe. FIELD_STRUCT_DESC: 18-inch steel stormdrain pipe through the levee 2-feet below the crown. Pump in ditch on the landward side. Siphon breaker on waterside shoulder. Electrical service pole at the landward toe. Permit No. 11546, 1976. FS Date: 5/13/2015					

Photo 2 of 2 : UCIP_SP_2016_45850_74100.jpg



WS view: slope on west side of pipe eroded at W/S toe. slope on east side of pipe OK.

LM Start	1.70	Rating **	C	Issue No.	961
LM End	1.76	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.804333 °	37.804615 °
				-121.393657 °	-121.392588 °
DWR ID	DWR_RD2058_01_s_2012_961				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
LMA removed vegetation fall 2015.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	1.82	Rating **	U	Issue No.	11
LM End	1.82	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.804785 °	37.804785 °
				-121.391524 °	-121.391524 °
DWR ID	DWR_RD2058_01_f_2013_11				
Comment Code					
MA : Material					
Inspector Comment					
Pile of concrete contains rebar on landside slope obstructing visibility and access.					

Photo 1 of 1 : SP_2016_RD2058_111_11_20160229_00005.jpg



View of the concrete with rebar placed on the landside slope.

LM Start	2.12	Rating **	M	Issue No.	975
LM End	2.12	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.803886 °	37.803886 °
				-121.386271 °	-121.386271 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46770 DS_ID:22706 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Leaky and damaged siphon breaker on waterside shoulder. Update: leaky siphon breaker at LM 2.14 repaired per Spring 2015 Inspection Report. Need to confirm repair was done at this location. FIELD_STRUCT_DESC: 16-inch steel stormdrain pipe 8.0-feet below the crown. Siphon Breaker on waterward shoulder. Pump on concrete sump on landside. Originally included in the 1964 O&M manual, SJR 10, March 1964. FS Date: 5/13/2015					

Photo 1 of 2 : UCIP_SP_2016_46770_45192.jpg



WS view: exposed steel pipe (right) on channel bank.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

Reclamation District No. 2058 Pescadero

View of the ditch at the landside levee toe.

Page 7 of 21

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	2.39	Rating **	A/W	Issue No.	16
LM End	2.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.802782 °	37.802782 °
				-121.381413 °	-121.381413 °
DWR ID	DWR_RD2058_01_s_2012_16				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberry growing on landside toe. The LMA maintains the shrub to allow visibility.					

No Photos

LM Start	2.44	Rating **	M	Issue No.	23
LM End	2.71	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.802608 °	37.801509 °
				-121.380638 °	-121.375805 °
DWR ID	DWR_RD2058_01_s_2016_23				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD2058_111_23_20160324_00040.jpg



View of the vegetation on the landside levee slope.

LM Start	2.61	Rating **	A/W	Issue No.	63
LM End	2.61	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.801962 °	37.801962 °
				-121.377684 °	-121.377684 °
DWR ID	DWR_RD2058_01_s_2012_63				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberry on waterside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	2.63	Rating **	A/W	Issue No.	64
LM End	2.63	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.801876 °	37.801876 °
				-121.377291 °	-121.377291 °
DWR ID	DWR_RD2058_01_s _ 2012_64				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	2.64	Rating **	A/W	Issue No.	65
LM End	2.64	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.801823 °	37.801823 °
				-121.377068 °	-121.377068 °
DWR ID	DWR_RD2058_01_s _ 2012_65				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	2.72	Rating **	A/W	Issue No.	66
LM End	2.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.801497 °	37.801497 °
				-121.375586 °	-121.375586 °
DWR ID	DWR_RD2058_01_s _ 2012_66				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	2.75	Rating **	A/W	Issue No.	17
LM End	2.75	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.801367 °	37.801367 °
				-121.375094 °	-121.375094 °
DWR ID	DWR_RD2058_01_f_2015_17				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
LMA removed vegetation fall 2015.					

Photo 1 of 1 : SP_2016_RD2058_111_17_20160229_00008.jpg



View of the willows on the waterside levee slope.

LM Start	3.53	Rating **	A/W	Issue No.	68
LM End	3.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.794396 °	37.794396 °
				-121.364944 °	-121.364944 °
DWR ID	DWR_RD2058_01_s_2012_68				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
The LMA maintains the shrub to allow visibility.					

No Photos

LM Start	3.72	Rating **	M	Issue No.	974
LM End	3.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.791856 °	37.791856 °
				-121.363514 °	-121.363514 °
DWR ID	DWR_RD2058_01_s_2012_974				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Flagged bushes obstructing visibility and access.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	3.80	Rating **	A/W	Issue No.	20
LM End	3.85	Issue Type +	Ob	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.790807 °	37.790088 °
				-121.362905 °	-121.362460 °
DWR ID	DWR_RD2058_01_s _ 2012_20				
Comment Code					
V8 : Environmental Requirements.					
Inspector Comment					
Revegetation site.					

Photo 1 of 1 : SP_2016_RD2058_111_20_20160229_00010.jpg



11/08/2011 Revegetation site, cannot trim or cut vegetation in this area.

LM Start	3.91	Rating **	A/W	Issue No.	22
LM End	3.91	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.789434 °	37.789434 °
				-121.361721 °	-121.361721 °
DWR ID	DWR_RD2058_01_s _ 2014_22				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
LMA removed vegetation in Fall 2015.					

Photo 1 of 1 : SP_2016_RD2058_111_22_20160229_00011.jpg



View of the tall vegetation on the landside levee slope and toe.

LM Start	3.96	Rating **	M	Issue No.	26
LM End	3.96	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.789128 °	37.789128 °
				-121.361042 °	-121.361042 °
DWR ID	DWR_RD2058_01_s _ 2012_26				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberry on landside hinge point.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	3.97	Rating **	A/W	Issue No.	69
LM End	3.97	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.789062 °	37.789062 °
				-121.360848 °	-121.360848 °
DWR ID	DWR_RD2058_01_s _ 2012_69				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	4.31	Rating **	M	Issue No.	24
LM End	5.58	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.789768 °	37.779132 °
				-121.354919 °	-121.339619 °
DWR ID	DWR_RD2058_01_s _ 2016_24				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD2058_111_24_20160324_00041.jpg



View of the vegetation on the landside levee slope.

LM Start	4.31	Rating **	A/W	Issue No.	71
LM End	4.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.789794 °	37.789794 °
				-121.354883 °	-121.354883 °
DWR ID	DWR_RD2058_01_s _ 2012_71				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

Reclamation District No. 2058 Pescadero

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	4.43	Rating **	M	Issue No.	1 (cont)	
LM End	4.47	Issue Type +	Ma	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR Erosion Survey			37.789810 °		37.789810 °
				-121.352490 °		-121.352490 °
DWR ID	DWR_RD2058_01_s_2016_1					
Comment Code						
Inspector Comment						
08/04/2015: No significant change observed.						
08/26/2014: No significant change observed.						
08/28/2013: No significant change observed.						
07/26/2012: The site has been visited, and no significant change has been observed.						
09/02/2011: This site was not visited due to the time limit.						
09/22/2010: No significant change observed. Minor pocket erosions are lined at the lower bank. Two large Oak and Willow trees are on mid-slope and bench. The remaining bench was re-measured and found to be approximately 10 feet. There was no indication of active erosion on site during the site visit.						
08/05/2010: Recommended for annual assessment and monitoring of the site during flood events, per CLRO.						
07/23/2009: No major change observed since last visit; site is a 200-ft. long near-vertical berm erosion; recommend annual assessment and monitoring of the erosion site, per CLRO CES Evaluation 2008 Report; Site # is the same site previously reported as RM4.0,LM4.51; previously rated "U".						
09/10/2008: Two large trees (2-3' DBH) with partial roots exposed.						
2007: Visited site 03/13/2007. [2015 Site ID:RD2058U01RM3.97]						

Photo 3 of 3 : SP_2016_RD2058_111_1_20160229_00003.jpg



Direct view of a pocket erosion site.

LM Start	4.77	Rating **	U	Issue No.	15
LM End	4.77	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.785862 °	37.785862 °
				-121.350303 °	-121.350303 °
DWR ID	DWR_RD2058_01_f_2013_15				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
The erosion has about a 3 foot vertical cut at the waterside levee toe.					

Photo 1 of 1 : SP_2016_RD2058_111_15_20160229_00007.jpg



View of the erosion at the waterside levee toe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	4.81	Rating **	C	Issue No.	18
LM End	4.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.785265 °	37.785265 °
				-121.350060 °	-121.350060 °
DWR ID	DWR_RD2058_01_f_2015_18				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
LMA trimmed the tree fall 2015.					

No Photos

LM Start	5.10	Rating **	U	Issue No.	29
LM End	5.10	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.783102 °	37.783102 °
				-121.345682 °	-121.345682 °
DWR ID	DWR_RD2058_01_s_2012_29				
Comment Code					
RA : Ramp					
Inspector Comment					
New ramp construction connecting dairy to levee. Construction of ramp results in a new pond on the landside of the levee. 2/21/2012, owner has said that he will contact the CVFPB to resolve this issue.					

Photo 1 of 3 : SP_2016_RD2058_111_29_20160229_00012.jpg



11/08/2011 New ramp has been constructed by Dairy farmer connecting his barns to the levee.

LM Start	5.10	Rating **	U	Issue No.	29 (cont)
LM End	5.10	Issue Type +	En	Location *	LS

Photo 2 of 3 : SP_2016_RD2058_111_29_20160229_00013.jpg



Completed new ramp constructed by Dairy farmer connecting his barns to the levee.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	5.10	Rating **	U	Issue No.	29 (cont)	
LM End	5.10	Issue Type +	En	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			37.783102 °	37.783102 °	
				-121.345682 °	-121.345682 °	
DWR ID	DWR_RD2058_01_s_2012_29					
Comment Code						
RA : Ramp						
Inspector Comment						
New ramp construction connecting dairy to levee. Construction of ramp results in a new pond on the landside of the levee. 2/21/2012, owner has said that he will contact the CVFPB to resolve this issue.						

Photo 3 of 3 : SP_2016_RD2058_111_29_20160229_00014.jpg



11/08/2011 New ramp has been constructed by Dairy farmer connecting his barns to the levee.

LM Start	5.29	Rating **	U	Issue No.	30
LM End	5.29	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.782268 °	37.782268 °
				-121.342257 °	-121.342257 °
DWR ID	DWR_RD2058_01_s_2012_30				
Comment Code					
RA : Ramp					
Inspector Comment					
Ramp constructed to dairy. Raised ramps, see issue 29 are creating new holding ponds for dairy at levee toe.					

Photo 1 of 3 : SP_2016_RD2058_111_30_20160229_00015.jpg



11/08/2011 Photo shows existing middle ramp to the levee which has been raised.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	5.29	Rating **	U	Issue No.	30 (cont)	
LM End	5.29	Issue Type +	En	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			37.782268 °		37.782268 °
				-121.342257 °		-121.342257 °
DWR ID	DWR_RD2058_01_s_2012_30					
Comment Code						
RA : Ramp						
Inspector Comment						
Ramp constructed to dairy. Raised ramps, see issue 29 are creating new holding ponds for dairy at levee toe.						

LM Start	5.29	Rating **	U	Issue No.	30 (cont)
LM End	5.29	Issue Type +	En	Location *	LS

Photo 2 of 3 : SP_2016_RD2058_111_30_20160229_00016.jpg



Completed new ramp constructed by Dairy farmer connecting his barns to the levee.

Photo 3 of 3 : SP_2016_RD2058_111_30_20160229_00017.jpg



11/08/2011 Photo shows view from the levee looking to the left of the middle ramp.

LM Start	5.63	Rating **	M	Issue No.	25
LM End	5.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.778515 °	37.778515 °
				-121.339136 °	-121.339136 °
DWR ID	DWR_RD2058_01_s_2016_25				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	5.97	Rating **	M	Issue No.	28
LM End	5.97	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.774886 °	37.774886 °
				-121.335122 °	-121.335122 °
DWR ID	DWR_RD2058_01_s_2016_28				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	6.09	Rating **	U	Issue No.	27
LM End	6.10	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.773629 °	37.773503 °
				-121.333688 °	-121.333550 °
DWR ID	DWR_RD2058_01_s_2016_27				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD2058_111_27_20160324_00042.jpg



View of the rodent burrows on the landside levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	6.46	Rating **	M	Issue No.	979
LM End	6.46	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.770158 °	37.770158 °
				-121.329430 °	-121.329430 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:45871 DS_ID:22701 EP_NO: 13262 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Owner needs to install signs at crossing. FIELD_STRUCT_DESC: Three 4-inch communication conduits encased in concrete through levee 3.0 feet below crown (Permit No. 13262, 1981). Sign on both banks of levee. Pipes visible under Manthey Rd Bridge at Paradise Cut. FS Date: 5/13/2015					

Photo 1 of 2 : UCIP_SP_2016_45871_73100.jpg



Pipes visible under Manthey Rd Bridge at Paradise Cut.

LM Start	6.46	Rating **	M	Issue No.	979 (cont)
LM End	6.46	Issue Type +	En	Location *	LS

Photo 2 of 2 : UCIP_SP_2016_45871_73101.jpg



Pipes visible under Manthey Rd Bridge at Paradise Cut.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	6.46	Rating **	M	Issue No.	980
LM End	6.46	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.770159 °	37.770159 °
				-121.329426 °	-121.329426 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:45768
DS_ID:25077
EP_NO: 13262
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: Owner needs to install signs at crossing.
FIELD_STRUCT_DESC: 2 of 3: 4-inch communication conduit encased in concrete through levee 3.0 feet below crown. Sign on both banks of levee. Manhole on both sides of Manthey Rd at utility crossing. (Permit No. 13262, 1981)
FS Date: 5/13/2015

LM Start	6.46	Rating **	M	Issue No.	980 (cont)
LM End	6.46	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_SP_2016_45768_74267.jpg



Pipes visible under Manthey Rd Bridge at Paradise Cut

Photo 2 of 2 : UCIP_SP_2016_45768_74268.jpg



Cuts in pavement visible appr. 450 ft from WS toe.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.58	03/22/2016 03/22/2016	Maksim Khashchuk

LM Start	6.46	Rating **	M	Issue No.	981
LM End	6.46	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			37.770158 °	37.770158 °
				-121.329430 °	-121.329430 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:45769
DS_ID:25078
EP_NO: 13262
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: Owner needs to install sign at crossing.
FIELD_STRUCT_DESC: 3 of 3: 4-inch communication conduit encased in concrete through levee 3.0 feet below crown. Sign on both banks of levee. Manhole on both sides of Mantney Rd at utility crossing. (Permit No. 13262, 1981)
FS Date: 5/13/2015

LM Start	6.46	Rating **	M	Issue No.	981 (cont)
LM End	6.46	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_SP_2016_45769_74270.jpg



Cuts in pavement visible apprx. 450 ft from WS toe.

Photo 2 of 2 : UCIP_SP_2016_45769_74271.jpg



Comm sign and Pac Bell manhole apprx. 600 ft from LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--